

41774 Main St. Box 191 • East Lynn, IL 60932 217-375-4244 • Fax: 217-375-4245 D 20' T36362 36 x 36 single brace Tower Make sure that on all four sides the Side Braces form W's all the way. At the end of the sections all the side braces go on the inside to allow tower tie and tie braces to fit. It is best to put all bolts out with nuts on the outside. Greene Welding and Hardware Inc. Rex A Green 2/21/2005 Greene Galvanized Stairs TITLE 217/375/4244 www.greenebinstairs.com IN-T00005 APPROVED DWG NO REV SIZE С T36361 Instructions SHEET 1 OF 2

Odd sections of a T36361 Tower



Parts List					
ITEM	QTY	PART NUMBER	DESCRIPTION		
1	4	SR1010 Siderail 2" x 2" x 120" 10 ga angle			
2	20	SB0036 side brace	1" x 2" x 42.25 10 ga angle		
3	4	SS0010 Splice	2" x 2" x 12" 10 ga angle		
4	4	TT0036 Tower Tie 36	ie 36 2" X 2" X 35.5 10 ga angle		
5	1	TB3636 Tie Brace 36	2" x 2" x 49.5" 10 ga angle		

## Even sections



Rex A Green 22/21/2005	Greene Welding and Hardware Inc.  Greene Galvanized Stairs	
	TITLE	217/375/4244 www.greenebinstairs.com
MFG		
APPROVED		
	SIZE	T36361 Instructions
		SHEET 2 OF 2